

CHIEF 113
KIS 4/01/96
9602280W 66001

HUNTINGTON BEACH POLICE DEPARTMENT
CASUALTY REPORT

Date of Report: 02/25/96 DR Number 96-004443

Code Offense Description
- DEATH REPORT
Date Occurred: SUN 02/25/96 at 19:30
Or Between: SUN 02/25/96 at 20:10
Discovered: SUN 02/25/96 at 20:10
Reported: SUN 02/25/96 at 20:10

Location: [REDACTED]
At or Near: [REDACTED]
Name of Place:
RD: 155 Beat: 10

CRIME SCENE INVESTIGATION | _____

CSI Conducted: Y by L. DZIEDZIC PIN 0677

INVESTIGATIVE ANALYSIS | _____

Is there a witness ? Y
Was there an arrest(s) ? N
Can the suspect vehicle be identified ? N
Was there significant or serious injury ? Y
Is there identifiable stolen property ? N Are there any ID numbers ?
Is there significant Modus Operandi ? Y
Is there significant Physical Evidence ? Y
Is there good probability of solution ? N
Is this a continuing problem ? N
Has any associated Stolen Vehicle
or Bike report been completed ? N

Officer A. GREENBURG PIN 1061 Supervisor [Signature]
Page 1 Date 2/26/96

169

HUNTINGTON BEACH POLICE DEPARTMENT
CASUALTY REPORT

960228C WE 6001

Date of Report: 02/25/96

DR Number 96-004443

PERSONS INVOLVED |

Involvement: VICTIM
Name: [REDACTED] Sex: F Race: [REDACTED]
Address: [REDACTED] DOB: 06/22/83 Age Range: [REDACTED]
Home Phone: [REDACTED] HOUSTON TX 77080
Occupation: STUDENT Work Phone: [REDACTED]
Employer Address: [REDACTED] Employed by: [REDACTED]
Relationship: [REDACTED] Interviewed? [REDACTED] Can ID? [REDACTED] Support Prosecution? [REDACTED]

...
Involvement: FINDER
Name: [REDACTED] Sex: M Race: [REDACTED]
Address: [REDACTED] DOB: 04/14/62 Age Range: [REDACTED]
Home Phone: [REDACTED] HOUSTON TX 77080
Occupation: [REDACTED] Work Phone: [REDACTED]
Employer Address: [REDACTED] Employed by: [REDACTED]
Relationship: [REDACTED] Interviewed? Y Can ID? [REDACTED] Support Prosecution? [REDACTED]

...
Involvement: [REDACTED]
Name: [REDACTED] Sex: M Race: [REDACTED]
Address: [REDACTED] DOB: 11/06/43 Age Range: [REDACTED]
Home Phone: [REDACTED] HUNTINGTON BEACH CA 92649
Occupation: CAR SALESMAN Work Phone: [REDACTED]
Employer Address: [REDACTED] Employed by: [REDACTED]
Relationship: [REDACTED] Interviewed? Y Can ID? [REDACTED] Support Prosecution? [REDACTED]

Details:

PROPERTY: See evidence report, same DR number.

On 02-25-96, at 2011 hours, I received a call of a possible child drowning at 4952 Maui Lane. I was approximately two blocks from the location when I received the call and responded code 3. I arrived at [REDACTED] less than one minute after I was dispatched.

Upon my arrival, I was directed to the rear yard of [REDACTED]. As I ran into the rear yard, I saw [REDACTED] lying on the wood deck adjacent to an in-ground jacuzzi. [REDACTED] was lying on the ground, on her back, with her head in an easterly direction. I saw her father, [REDACTED] leaning over [REDACTED] doing CPR. I also saw a female doing compressions on [REDACTED]. This female was identified by Officer MARTIN, see his supplemental report for details.

Officer A. GREENBURG

PIN 1061

Supervisor [REDACTED]

Page 2

Date 2/26/96

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443
printed on 02/26/96 at 12:14

170

HUNTINGTON BEACH POLICE DEPARTMENT
CASUALTY REPORT

960228C WF 6001

Date of Report: 02/25/96

DR Number 96-004443

As I approached [REDACTED], I noticed that she was blue in color. I checked and saw that she was not breathing and had no pulse. I also noted that [REDACTED] had vomited.

I then removed my portable CPR mask which I carry on my person and cleared [REDACTED] airway and relieved [REDACTED] from doing CPR on his daughter. I continued to do two person CPR with the female that was already doing the chest compressions. I continued the CPR until Huntington Beach Medic Engine #48 arrived. I then continued to assist Huntington Beach Medic Engine #48 with CPR, until Huntington Beach Ambulance #42 transported [REDACTED] to Huntington Beach Medical Center.

After [REDACTED] was transported to Huntington Beach Medical Center, I walked back into the backyard and examined the jacuzzi area. I saw that the jacuzzi was an approximate 7 foot octagon shaped in-ground jacuzzi, with a wood deck around it. I noticed that the jacuzzi cover was lying on the wood deck, just west of the jacuzzi. I also noticed that the jacuzzi light was on, but the jets had been turned off. I looked inside the jacuzzi and saw a pair of scissors with orange handles resting on the seat at the east end of the jacuzzi. I then noticed a large mass of brown hair stuck in what looked like a drain cover, also on the east wall of the jacuzzi, below the seat, approximately one foot from the bottom of the jacuzzi. For further details, refer to CSI report and additional supplemental reports by other officers who responded to the location.

I then spoke with [REDACTED], the father of [REDACTED]. [REDACTED] told me that he and [REDACTED] live in [REDACTED] and are in Huntington Beach on vacation, staying with [REDACTED].

[REDACTED] told me that on 02-25-96, between 1930 hours and 1945 hours, he was unsure of the exact time, [REDACTED] had just finished dinner and asked if she could take a jacuzzi. [REDACTED] said that his stepfather, [REDACTED] then went into the backyard and removed the cover of the jacuzzi and turned the jacuzzi heater on for [REDACTED].

[REDACTED] said approximately 30 minutes later, around 8 PM, his mother, [REDACTED] asked where [REDACTED] was and said that she was not in the jacuzzi. [REDACTED] and [REDACTED] then went out, checked the jacuzzi and the backyard for [REDACTED] while [REDACTED] walked out to the front yard and checked the front yard for [REDACTED] whereabouts. [REDACTED]

Officer A. GREENBURG

PIN 1061

Supervisor

Page 3

Date

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443
printed on 02/26/96 at 12:14

171

960228LWE6001

HUNTINGTON BEACH POLICE DEPARTMENT
CASUALTY REPORT

Date of Report: 02/25/96

DR Number 96-004443

██████████ told me that he then went back inside the house and checked the entire interior of the house for ██████████. Unable to find her, he decided to go out into the backyard and double check the jacuzzi for ██████████.

He walked back in the backyard again, this time with his stepfather, ██████████. ██████████ turned on the jacuzzi light, at which time ██████████ noticed ██████████ face up in the bottom of the jacuzzi with her head pointed in an easterly direction. ██████████ said he tried to pull ██████████ out of the pool, but was unable to due to the fact that her hair was caught in the drain of the jacuzzi. He then yelled for someone to get him a pair of scissors. ██████████ brought ██████████ the scissors, at which time ██████████ cut ██████████ hair in order to retrieve ██████████ from the pool. Once out of the pool, ██████████ immediately started CPR on ██████████. ██████████ continued CPR until I relieved him and continued the CPR myself.

I then spoke with ██████████ the step-grandfather of ██████████.

██████████ told me that on 02-25-96, around 1930 hours, he was unsure of the exact time, he had just finished dinner and went to play cards with ██████████ and other family members who were at his house located at ██████████. Approximately ten minutes after he started to play cards, he was unsure of the time, he believes it was around 7:30 PM, ██████████ asked ██████████ if he would turn on the jacuzzi for her so she could take a jacuzzi. ██████████ said yes to ██████████ and walked out to the backyard, removed the jacuzzi cover from the jacuzzi and turned on the jacuzzi heater, filter, lights and jacuzzi bubble jets. He then went back inside and asked ██████████ if ██████████ would be okay alone in the jacuzzi. ██████████ told ██████████ yes, she'll be fine in the jacuzzi. ██████████ then continued their card game.

Approximately 20 minutes after ██████████ turned on the jacuzzi for ██████████, ██████████ left the card table and went to the restroom. When she came from the restroom, she said ██████████ is not in the jacuzzi. ██████████ told me that ██████████, ██████████ and himself talked for about 5 minutes at the card table about where ██████████ could be.

██████████ then walked out to the front yard and checked the front yard for ██████████, while ██████████ and ██████████ checked the entire inside of the house, then checked the backyard and jacuzzi for ██████████. ██████████ told me that he and his wife, ██████████, walked in the backyard to the jacuzzi, looked into the jacuzzi and noticed that the light of the jacuzzi was on and the jacuzzi bubble jets were on. ██████████ turned off the jacuzzi bubble jets and looked back into the jacuzzi and still did not see Krista inside the

Officer A. GREENBURG

PIN 1061

Supervisor MR

Page 4

Date 2/26/96

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443
printed on 02/26/96 at 12:1

172

HUNTINGTON BEACH POLICE DEPARTMENT
CASUALTY REPORT

960228CWE 6001

Date of Report: 02/25/96

DR Number 96-004443

jacuzzi. [REDACTED] and [REDACTED] then went back into the house.

As [REDACTED] walked back to the house, [REDACTED] had returned from the front yard and decided to double check his backyard. [REDACTED] asked [REDACTED] if he was sure that [REDACTED] was not in the jacuzzi and [REDACTED] said, yes. [REDACTED] then walked over to the jacuzzi and yelled that he had found [REDACTED]. [REDACTED] looked outside the backyard and saw [REDACTED] try to pull [REDACTED] out of the jacuzzi. He noticed that [REDACTED] hair was stuck in the drain at the east end of the jacuzzi. [REDACTED] then yelled for someone to bring him a pair of scissors, at which time [REDACTED] ran inside, retrieved a pair of scissors and brought them to [REDACTED]. [REDACTED] then used the scissors to cut [REDACTED] hair, enabling him to remove [REDACTED] from the jacuzzi.

[REDACTED] told me that once [REDACTED] removed [REDACTED] from the jacuzzi, he laid her on the deck, next to the pool, and immediately started CPR, at which time his neighbor, a nurse from across the street by the name of [REDACTED] came over to the house and assisted [REDACTED] with CPR. For further details regarding the interview of [REDACTED] refer to Officer MARTIN's supplemental report.

Officer MARTIN, Officer COTTRIEL and Officer KLEMKE then drove to Huntington Beach Medical Center to conduct a follow-up investigation. For further details, refer to their supplemental reports.

No further investigation was conducted by me at this time.

Officer A. GREENBURG

PIN 1061

Supervisor

Page 5

Date

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443
printed on 02/26/96 at 12:1

173

AUTHORIZATION AND REQUEST FOR POLICE REPORT

ok to give copy per
Sgt. Burgess

960228CWE6001

TO WHOM IT MAY CONCERN:

RE: Driver's License #:

C 0161475

Location of Accident:

[REDACTED]

City of / County of:

Huntington Beach -

Date of Accident:

Feb 25, 1996

Parties Involved:

[REDACTED]

Kindly permit my attorneys, KESSLER & ASSOCIATES, or their representative, to examine and make copies of, and at their request, furnish them with copies of any police reports, photographs or other information you may have concerning the above referenced accident.

A copy of this signed Authorization bearing a copy of my signature shall be as effective and valid as the original.

DATED: 1/74

SIGNED: [Signature]

[REDACTED]

PLEASE MAIL REPORT TO:

GARY ALAN KESSLER, ESQ.
KESSLER & ASSOCIATES
4570 Campus Drive, Suite 17
Newport Beach, CA 92663
(714) 252-1168



HUNTINGTON BEACH POLICE DEPARTMENT
INCIDENT REPORT NARRATIVE

CASE #
96-04443
Page **1** of **4**

NARRATIVE: (List DRUGS, DOCTOR(S), HOSPITAL and CORONER, etc. in Casualty Report narratives)

SUPPLEMENTAL:

960228 CUE6001

VICTIM:

[REDACTED]
6-22-83

[REDACTED]
HOUSTON, TX 77080
[REDACTED]

ON 2-25-96, AT APPROX. 2045 HRS, I WAS
REQUESTED BY SGT. STUART TO RESPOND TO
[REDACTED]

UPON ARRIVAL, I CONTACTED SGT. STUART
(WHO WAS IN THE LIVINGROOM. WE WALKED OUT-
SIDE, TO THE BACKYARD, AND I SAW OFFICER
COTTREIL AND OFFICER MARTIN STANDING NEXT
TO THE JACUZZI. OFFICER COTTREIL WAS USING
THE "SKIMMER" TO RETRIEVE THE VICTIM'S HAIR
THAT HAD BEEN CAUGHT IN THE DRAIN
COVER.

OFFICER COTTREIL HAD REMOVED THE DRAIN
COVER, WHICH I TOOK POSSESSION OF AND
WAS LATER BOOKED INTO EVIDENCE AS ITEM #2.
THE HAIR THAT WAS COLLECTED FROM THE JACUZZI
AND DRAIN COVER WERE ALSO BOOKED INTO
EVIDENCE AT A LATER TIME.

Officer: KLEMKE

PIN: 182

Supervisor: [Signature]

Date: 2/26/96

175



HUNTINGTON BEACH POLICE DEPARTMENT
INCIDENT REPORT NARRATIVE

CASE #
96-04443
Page 2 of 4

960228 CWF 6001

NARRATIVE: (List DRUGS, DOCTOR(S), HOSPITAL and CORONER, etc. in Casualty Report narratives)

I WAS THEN REQUESTED TO GO TO
"HUNTINGTON BEACH MEDICAL CENTER" TO
INTERVIEW OTHER FAMILY MEMBERS.

UPON ARRIVAL, I WAS NOTIFIED BY SGT.
TIDRICK THAT THE FAMILY HAD DECIDED TO GO
BACK HOME. OFFICER COTTREIL, WHO ALSO SHOWED
UP AT "H.B.M.C." THEN WENT BACK TO THE
RESIDENCE TO INTERVIEW THE REST OF THE
FAMILY MEMBER'S.

I STAYED AT "H.B.M.C." AWAITING THE
ARRIVAL OF THE CORONER. AT APPROX. 2200 HRS.,
SENIOR DEPUTY CHRISTY WURSTER-McCOY (3.29.70)
ARRIVED AND TOOK CUSTODY OF THE VICTIM.
WHILE DEPUTY CHRISTY WURSTER-McCOY WAS
CONDUCTING HER INVESTIGATION, SHE TOLD ME
THAT SHE DID NOT SEE ANY SUSPICIOUS
TRAUMA. THERE WERE TWO 1" SCRATCHES ON
THE INNER PORTION OF HUMPHREY'S LEFT
SHIN. ONE SCRATCH WAS APPROX. 1" x 1/2" (w) AND
APPROX. 3 1/2" ABOVE THE ANKLE. THE OTHER
SCRATCH WAS JUST ABOVE THIS OTHER ONE
AND IT WAS APPROX. 1" (L) x 1/4" (w). DEPUTY CHRISTY
WURSTER-McCOY STATED THAT THESE SCRATCHES
LOOKED "FRESH", HOWEVER, DUE TO THE VICTIM
BEING IN WATER SHE WAS NOT STATING THIS
TO BE FACT AT THIS TIME.

176

Officer: KLEMKE

PIN: 182 Supervisor:

Date: 1 / 1



HUNTINGTON BEACH POLICE DEPARTMENT
INCIDENT REPORT NARRATIVE

CASE #
96-04443
Page 3 of 4

NARRATIVE: (List DRUGS, DOCTOR(S), HOSPITAL and CORONER, etc. in Casualty Report narratives)

AT APPROX. 2225 HRS., DAN NEWTON
FROM THE CORONER'S OFFICE REMOVED THE
VICTIM'S BODY FROM "H.B.M.C."

I THEN RESPONDED TO THE "HUNTINGTON
BEACH POLICE DEPARTMENT" WHERE THE
PROPERTY WAS BOOKED INTO EVIDENCE.

NO FURTHER DETAILS, REFER TO
OFFICER GREENBURG AND MARTIN'S REPORTS.
SEE DEPUTY CHRISTY WURSTER-MCCOY REPORT
FILED UNDER 96-01341-WU.

Officer: KLEMKE

PIN: 182 Supervisor: *JK*

Date: 1 / 1

Officer: KIEMKE PIN: 82 Supervisor: [Signature] Date: 1 / 1

960228CWE 6001

HUNTINGTON BEACH POLICE DEPARTMENT
SUPPLEMENTAL REPORT

Date of Report: 02/25/96

DR Number 96-004443

Code Offense Description
- DEATH REPORT

Date Occurred: SUN 02/25/96 at 19:30
Or Between: at
Discovered: at
Reported: SUN 02/25/96 at 20:10

Location: [REDACTED]
At or Near:
Name of Place:
RD: Beat:

PERSONS INVOLVED |

Involvement: WITNESS Sex: F Race:
Name: [REDACTED] DOB: 10/03/42 Age Range:
Address: [REDACTED] HUNTINGTON BEACH CA 92649
Home Phone: [REDACTED] Work Phone:
Occupation: Employed by:
Employer Address:
Relationship: Interviewed? Y Can ID? Support Prosecution?

Involvement: WITNESS Sex: M Race:
Name: [REDACTED] DOB: 11/01/33 Age Range:
Address: [REDACTED] HUNTINGTON BEACH CA 92649
Home Phone: [REDACTED] Work Phone: [REDACTED]
Occupation: Employed by:
Employer Address:
Relationship: Interviewed? Y Can ID? Support Prosecution?

Involvement: WITNESS Sex: F Race:
Name: [REDACTED] DOB: 02/12/37 Age Range:
Address: [REDACTED] HUNTINGTON BEACH CA 92649
Home Phone: [REDACTED] Work Phone:
Occupation: Employed by:
Employer Address:
Relationship: Interviewed? Y Can ID? Support Prosecution?

Officer D. MARTIN

PIN 1046

Supervisor *[Signature]*

Page 1

Date *2-26-96*

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443/1
printed on 02/26/96 at 16:19

179

960228 CUE 600j

HUNTINGTON BEACH POLICE DEPARTMENT
SUPPLEMENTAL REPORT

Date of Report: 02/25/96

DR Number 96-004443

Details:

On 02-25-96 at 2010 hours, Dispatch broadcast a medical aid call at [REDACTED] for a report of a 12-year-old who was found in a jacuzzi. Officer COTTRIEL, #253, and I responded to the location to assist Officer GREENBURG who had been assigned the call.

Upon our arrival at the location, Officer GREENBURG and Huntington Beach Fire Department were already at the scene. We entered the house and saw [REDACTED] on the floor in the back living room. Huntington Beach Fire Department was attempting to resuscitate the unconscious victim. Officer GREENBURG asked me to assist him with his investigation.

Huntington Beach Fire Department transported [REDACTED] to Huntington Beach Medical Center. Officer COTTRIEL and I went to Huntington Beach Medical Center and were advised by the E.R. staff that Doctor William PARK pronounced the victim dead at 2043 hours.

Officer KLEMKE responded to Huntington Beach Medical Center and stood by with the victim and awaited the arrival of the coroner. See Officer KLEMKE's supplemental report for further details.

Officer COTTRIEL and I responded back to [REDACTED] and I met with [REDACTED].

She told me that at about 1940 hours this evening, the family had finished eating dinner and had gone into the garage to play cards. [REDACTED] came into the garage and asked [REDACTED] if she could go sit in the jacuzzi. [REDACTED] told her that it would be alright and [REDACTED] went to put on her bathing suit.

About 15 minutes later, [REDACTED] went to the bathroom and looked outside the bathroom window into the backyard. [REDACTED] noticed that [REDACTED] was not in the jacuzzi. She went back into the garage and asked the other adults where [REDACTED] had gone. Since none of the adults knew where [REDACTED] had gone, they began to search the house for her.

[REDACTED] and her husband, [REDACTED], walked outside to the jacuzzi and noticed that the jacuzzi lights and bubbles were on. They looked inside the jacuzzi and did not see [REDACTED]. [REDACTED] turned off the jacuzzi and the jacuzzi lights, then continued to search the house and the surrounding neighborhood for [REDACTED].

At about 2010 hours, [REDACTED] father, [REDACTED], decided he wanted to check the jacuzzi one more time. [REDACTED] went out to the backyard

Officer D. MARTIN

PIN 1046

Supervisor

[Signature]

Page 2

Date

2-26-96

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443/1
printed on 02/26/96 at 16:19

180

960228 CWE 6001

HUNTINGTON BEACH POLICE DEPARTMENT
SUPPLEMENTAL REPORT

Date of Report: 02/25/96

DR Number 96-004443

with [REDACTED] and [REDACTED]. [REDACTED] turned on the jacuzzi light and saw his daughter lying at the bottom of the jacuzzi. He reached into the jacuzzi and grabbed his daughter and tried to pull her out of the water, however, [REDACTED] hair was stuck in the filter opening at the bottom of the jacuzzi. [REDACTED] yelled to [REDACTED] and told him to go get some scissors. [REDACTED] ran inside the house and returned several seconds later with a pair of scissors. [REDACTED] used the scissors to cut away his daughter's hair and free her from the jacuzzi's filter. He was then able to pull his daughter out of the jacuzzi and laid her on the deck.

[REDACTED] immediately began to perform CPR as [REDACTED] walked into the house. [REDACTED], who is a nurse, shouted for [REDACTED] to call 911. [REDACTED] then ran over to [REDACTED] and began to assist with CPR.

[REDACTED] said she spoke to the 911 operator for several seconds and soon afterwards, Officer GREENBURG arrived at the scene and began to assist with CPR. See Officer GREENBURG's report for further details.

I contacted [REDACTED] and [REDACTED] who are [REDACTED] and [REDACTED] neighbors.

[REDACTED] told me that she and her husband were walking across the street to go to [REDACTED] and [REDACTED] house to play cards. [REDACTED] said she met [REDACTED] on the front lawn of the [REDACTED] residence. [REDACTED] told [REDACTED] and [REDACTED] that it appeared that [REDACTED] had wandered away from the house and the other family members were looking for her. Several minutes later, [REDACTED] heard several family members shouting inside the house. [REDACTED] ran inside the house and saw [REDACTED] attempting to perform CPR on [REDACTED]. She immediately ran over and began to assist [REDACTED] with CPR. Less than a minute later, Officer GREENBURG arrived at the location and also began to assist [REDACTED] with CPR.

Officer COTTRIEL and I inspected the jacuzzi. I observed a large amount of human hair stuck to the jacuzzi filter cover that was located on the side of the jacuzzi, near the bottom. Officer COTTRIEL and I removed the jacuzzi's filter cover and retrieved the hair. We turned the hair and the filter cover over to CSI Officer DZIEDZIC, #677. Officer COTTRIEL and I tested the jacuzzi water temperature with a pool thermometer and noted that the temperature was 94 degrees at 2122 hours. I also looked at a nearby thermometer and noted that the ambient air temperature was 52 degrees.

Officer D. MARTIN

PIN 1046

Supervisor

Page 3

Date

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443/1
printed on 02/26/96 at 16:19

181

HUNTINGTON BEACH POLICE DEPARTMENT
SUPPLEMENTAL REPORT

960228 CAP 6001

Date of Report: 02/25/96

DR Number 96-004443

Officer COTTRIEL and I responded back to Huntington Beach Medical Center and met with Orange County Coroner WURSTER, employee #53. WURSTER told me she had examined [REDACTED]'s body and had determined that the cause of death was drowning. She also said she had found no obvious evidence of other trauma. WURSTER gave me an Orange County Coroner's case number of 96-01341.

[REDACTED] was treated at the scene by paramedics Don CONE and Steve TAYLOR. [REDACTED] was transported to Huntington Beach Medical Center by ambulance 42.

I did no further investigation.

Officer D. MARTIN

PIN 1046

Supervisor 

Page 4

Date 2-26-96

TYPED BY: P. BROWN /420805
HBPD FORM OFFENSE (rev. 12/91)

96-004443/1
printed on 02/26/96 at 16:19

182

HUNTINGTON BEACH FIRE

FIRE REPORT NUMBER 603053-00

PRINTED ON 03/20/96 AT 12:51

EXTRACT #4
KTS 3/24/03/96
9607080006001

Multi Agency Incident Number : HTB-96-603053
Incident Date : 02/25/96
Dispatch Time : 20:11:17
Arrival Time : 20:14:52
End Time : 21:35:43
Number of Days : 0
First In Company : HME48
District : HB

Types of Situations Found

1 : 32 EMERGENCY MEDICAL CALL
2 :
3 :
4 :

Automatic or Mutual Aid : 8 NO AUTO/MUTUAL AID REC.OR PROV
Method of Alarm : 7 TELEPHONE TIE-LINE TO F.D.
Type of Weather :
Air Temperature :
Property Management : 1 PRIVATE TAX-PAYING PROPERTY

Incident Location Information

Location :
Room/Apt :
Zip Code : 92649 Grid : :155
Census Tract : 000000
Fire Hazard Severity Zone :

Total Fire Service Personnel Responded

Career : 6
Volunteer : 0

Total Fire Apparatus Responded

Engine : 0
Truck : 0
Rescue/Medical : 0
Other : 2

Reporting Officer personnel # : 0083 FREEMAN SCOTT B.

Reporting Officer unit # : HME48

Officer in Charge if Diff. :

Fire Investigator name/city :

83

HUNTINGTON BEACH FIRE

FIRE REPORT NUMBER 603053-00

PRINTED ON 03/20/96 AT 12:51

960 228 CWF 6001

Incident Owner/Resident/Other Information - Person 1

Person Type Code :
Name :
Telephone :
Street :
City :
State/Zip :

Incident Owner/Resident/Other Information - Person 2

Person Type Code :
Name :
Telephone :
Street :
City :
State/Zip :

Incident Property Information

General Property Use : 41 1 OR 2 FAMILY RESIDENTIAL USE
Specific Property Use : 411 ONE-FAMILY RESIDENCE, YEAR-ROUND USE
Building Code Occ Type :
Structure Type :
Structure Status :
Occupied at Incident Time . : .

Mobile Property Involved

Property Type : 98 MOBILE PROPERTY NOT APPLICABLE
Vehicle License No. :
Vehicle Lic State Year :
Make :
Model :
D.O.T. :
Vehicle ID number :
Drivers License #/State ... :

960 228 CWF 6001

HUNTINGTON BEACH FIRE

FIRE REPORT NUMBER 603053-00

PRINTED ON 03/20/96 AT 12:51

Fire Service Casualty

Number of Injuries : 0

Number of Fatalities : 0

Non-Fire Service Casualty

Number of Injuries : 0

Number of Fatalities : 0

Other Types of Action Taken

1 : 33 PROVIDE EMERGENCY MEDICAL SERV

2 : 36 TRANSPORT

3 :

4 :

Special Studies Local

1/2/3/4 :

Special Studies Statewide

1/2 :

HUNTINGTON BEACH FIRE

FIRE REPORT NUMBER 603053-00

PRINTED ON 03/20/96 AT 12:51

EMS INFORMATION

Number of Patients : 1
Highest Level of Care Capable/Provided at the Scene
Fire Capable : 6 ADVANCE LIFE SUPPORT
Fire Provided : 6 ADVANCE LIFE SUPPORT
Other Capable :
Other Provided :
E.M.S. Type of Situation Found
1 : 84 DROWNING
2 :
3 :
4 :
Number of Patients Transported By
Fire Department : 1
Private Ambulance : 0
Coroner : 0
Other : 0

960228 C W E 6001

HUNTINGTON BEACH FIRE

960228 CWF 6001

FIRE REPORT NUMBER 603053-00

PRINTED ON 03/20/96 AT 12:51

UNIT	TYPE	DISPATCH	RESPOND	ON-SCENE	TRANSPORT	AT HOSP.	AVAILABLE
------	------	----------	---------	----------	-----------	----------	-----------

HME48	M	20:11:17	20:11:54				20:49:27
HA42	HA	20:11:18	20:11:57	20:16:47			21:35:43

Complainant phone: 8403164 20:11:02

Response area: 155 20:11:02

DROWNING (CEK) 20:11:08

CPR IN PROGRESS (CEK) 20:11:49

12 YR FEMALE FOUND IN JACUZZI (CEK) 20:13:09

PD ON SCENE (CEK) 20:13:12

B6 HEMC (NRF) 20:18:28

*** Original Location: 4952 MAUI CR

***Notes Added 02/25/96 On Port 214 at 21:49 by FREEMAN SCOTT B.

PATIENT FOUND UNCONSCIOUS IN JACUZZI. SHE WAS PULLED OUT AND CPR WAS STARTED BY HBPD. ALS PROTOCOL WAS FOLLOWED AND PATIENT WAS TRANSPORTED TO HEMC.

***Notes Added 02/29/96 On Port 214 at 09:27 by FREEMAN SCOTT B.

***Notes Added 02/29/96 On Port 214 at 10:10 by FREEMAN SCOTT B.

ON FEB 25, 1996 AT 2011 HRS HME48 RESPONDED TO A POSSIBLE DROWNING AT

UPON ARRIVAL HME48 CREW ENTERED THE RESIDENCE TO FIND TWO HBPD OFFICERS PERFORMING CPR ON A 12 Y/O GIRL. WE WERE INFORMED BY THE FAMILY THAT SHE WAS PULLED FROM A JACUZZI AFTER THEY FOUND HER UNCONSCIOUS

AT THE BOTTOM OF THE SPA. THE GIRLS FATHER STATED THAT HER HAIR WAS CAUGHT IN

THE JACUZZI DRAIN AND THEY WERE FORCED TO CUT IT SO THEY COULD REMOVE HER.

IT WAS ESTIMATED THAT SHE COULD HAVE BEEN IN THE SPA FOR 15 TO 30 MINUTES.

HME48 PERFORMED ALL PARAMEDIC ALS PROCEDURES IN AN ATTEMPT TO REVIVE HER.

SHE

WAS TRANSPORTED TO HEMC VIA HA42 WITH PARAMEDICS. SHE WAS PRONOUNCED DEAD AT

THE HOSPITAL BY THE E.R. DOCTOR. NOTE: DUE TO THE FAMILY SCREAMING AT US

UPON OUR ARRIVAL OUR AT SCENE BUTTON WAS NOT PUSHED. IT WAS DETERMINED FROM

OUR PRE HOSPITAL MIC FORM THAT OUR ARRIVAL TIME WAS 20:15. FOUR MINUTES

AFTER

THE INITIAL DISPATCH. THE SCENE WAS RELEASED TO HBPD FOR INVESTIGATION.

CAPT. SCOTT FREEMAN

187

960228CWEG001



ORANGE COUNTY EMERGENCY MEDICAL SERVICES

SERVICES

PRE-HOSPITAL CARE REPORT

EMT ONLY ☐ CH CONTRACT ☐
FALL ONLY ☐ NO BH CONTACT ☐

INCIDENT NUMBER

60305

<input type="checkbox"/> MILD	<input type="checkbox"/> MODERATE	<input type="checkbox"/> ACUTE MEDICAL	<input type="checkbox"/> MILD	<input type="checkbox"/> MODERATE	<input type="checkbox"/> ACUTE MEDICAL	<input type="checkbox"/> NEURO	<input type="checkbox"/> FIELD DEATH	<input type="checkbox"/> BURN	<input type="checkbox"/> DNR	<input type="checkbox"/> MVI	DISTRICT	UNIT	BLK	YEAR	MONTH	DAY	HOUR	MIN	SEC
-------------------------------	-----------------------------------	--	-------------------------------	-----------------------------------	--	--------------------------------	--------------------------------------	-------------------------------	------------------------------	------------------------------	----------	------	-----	------	-------	-----	------	-----	-----

NAME	INCIDENT LOCATION
------	-------------------

AGE	DOB	SEX	WEIGHT	KG	LBS	COMM PROB	LANG BARR	MAILING ADDRESS	PHONE/CELL
-----	-----	-----	--------	----	-----	-----------	-----------	-----------------	------------

CHIEF COMPLAINT	MED HISTORY
-----------------	-------------

HX OF ILLNESS/INJ	MEDS
-------------------	------

PRIMARY SURVEY	ALLERGIES
----------------	-----------

<input type="checkbox"/> NORMAL	<input type="checkbox"/> ALERT	<input type="checkbox"/> ORIENTED	<input type="checkbox"/> PERSON	<input type="checkbox"/> PLACE	<input type="checkbox"/> SITUATION	<input type="checkbox"/> NORMAL	<input type="checkbox"/> WARM	<input type="checkbox"/> COOL	<input type="checkbox"/> HOT	<input type="checkbox"/> COLD
---------------------------------	--------------------------------	-----------------------------------	---------------------------------	--------------------------------	------------------------------------	---------------------------------	-------------------------------	-------------------------------	------------------------------	-------------------------------

PUPILS	PERL	GLUCOSE	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA
--------	------	---------	----------	----------	----------	----------	----------	----------	----------	----------

GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA	GLAUCOMA
----------	----------	----------	----------	----------	----------	----------	----------	----------	----------	----------

TIME	PULSE	REPS	B/P	EKG	TIME	TREATMENT / RESPONSE
------	-------	------	-----	-----	------	----------------------

INITIAL ASSESSMENTS	COMMENTS/DETAILS	ALARM	902-H	2026	2037	REC CTR	TRANSPORT	COMM MODE
---------------------	------------------	-------	-------	------	------	---------	-----------	-----------

960228CWE6001

PATIENT NAME (FIRST) (LAST)
603053
INCIDENT NUMBER
CONE 137 137
COMPLETED BY: (PRINT NAME) (PIN)

ENGINES		TRUCKS	AMB
<input type="checkbox"/> HME - 41	<input type="checkbox"/> HME - 47	<input type="checkbox"/> HQ - 42	<input type="checkbox"/> HA - 41
<input type="checkbox"/> HME - 42	<input checked="" type="checkbox"/> HME - 48	<input type="checkbox"/> HQ - 45	<input checked="" type="checkbox"/> HA - 42
<input type="checkbox"/> HME - 43	<input type="checkbox"/> HE - 241	<input type="checkbox"/> VQ - 31	<input type="checkbox"/> HA - 45
<input type="checkbox"/> HME - 44	<input type="checkbox"/> VME - 31		<input type="checkbox"/> _____
<input type="checkbox"/> HME - 45	<input type="checkbox"/> VME - 32		

#FD008 (11/95) SUBMIT ENTIRE FORM WITH BLUE & GREEN COPY OF MIC FORM TO FIRE MED

189

ORANGE COUNTY SHERIFF-CORONER
1071 W. SANTA ANA BLVD.
SANTA ANA, CA 92703

EXHIBIT # 5
KTB 3/22/96
960228066001

RAD GATES, SHERIFF-CORONER

CASE SUMMARY

DECEDENT: [REDACTED] CASE NO.: 96-01341-WU
RESIDENCE: [REDACTED] PD: HBPD
CITY: [REDACTED] DR: 96-04443
AGE: 12 years DOB: 06-22-83 STATE: TX 77080
RACE: White SEX: Female
OCCUPATION: Student
RELATIVES: Father: [REDACTED]
ADDRESS: [REDACTED]
CITY/STATE: [REDACTED]

CLASSIFICATION: Accident SUBCLASS CODE: MECAP
DATE OF DEATH: 02-25-96 DATE OF INJURY: 02-25-96
TIME OF DEATH: 2043 hrs. TIME OF INJURY: Unknown hrs.

PLACE OF DEATH: Huntington Beach Medical Center
ADDRESS: 17772 Beach Blvd.
CITY: Huntington Beach, CA 92647
INJURY MODE: Spa
INJURY TYPE: Drowning/spa/private residence
INJURY SITE: Private residence/backyard spa
INJURY ADDRESS: [REDACTED]
INJURY CITY: [REDACTED]

ADMITTED FROM: Private residence
ADDRESS: [REDACTED]
CITY: [REDACTED]

CAUSE OF DEATH: Fresh water drowning

OTHER COND.: None

INVESTIGATOR: CHRISTY L. WURSTER
PATHOLOGIST: Joseph J. Halka, M.D.
AUTOPSY DATE: 02-26-96 TOX RETURNED: 03-14-96 MICRO RETURNED:

DRUGS FOUND PRESENT IN SIGNIFICANT LEVELS:

B/A LEVEL	0.00%
BENZOYLECGONINE	N
COCAINE	N
MORPHINE	N
CODEINE	N
CE	N
METHAMPHETAMINE	N
OTHER DRUGS	N
POISON	N

DATE CERTIFICATE ISSUED: 02-26-96

DATE CERTIFICATE AMENDED: - -

190

EXHIBIT # 6
KTS 3/21/96
960228CWE6001

Draw your own conclusions.

THE MARIAH AIR PUMP: a new direction for blowers.

Hydro Air Industries—the new idea company—is making history with the revolutionary Mariah Air Pump, today's standard of excellence. It's not just another air blower, but the first air pump with a self-cooling bypass motor that eliminates overheating and water damage, and permits trouble-free performance year after year.

Developed specially for spas and hot tubs, the Mariah's unique motor design provides the industry with a new measure of safety, and an end to warranty problems. Universal installation of the unit (side or bottom outlets) requires plumbing connections of only 1½".

If you've put up with blower problems long enough, you're ready for the Mariah Air Pump. For details, contact us at Hydro Air Industries—the new idea company.

A. Air is drawn in under the lid and down the air intake tube, rather than over an electric motor as in conventional blower designs. Overheating is eliminated.

B. With the Mariah's peripheral discharge design, air from the intake tube is pumped through the impellers (stages) and released out the lowered side of the unit.

C. The gasket seal is watertight.

D. The Mariah incorporates the first air pump motor designed specifically for the spa/hot tub industry. The electrical component is safely located in the upper level to prevent water damage and the possibility of electrical shock in the event condensation or water backflow enters the air chamber. The motor has its own cooling system, unlike conventional units which depend on the air flow to retard overheating.

E. Thermal overload protection prevents overheating or damage to the unit during long runs and extended use.

F. Acoustical foam insulation ensures quiet operation.

G. Junction box, switch, and clear Lexan cover included.

H. Side installation option.



THE NEW IDEA COMPANY

HYDRO AIR INDUSTRIES INC. 

1317 W. GROVE AVE., ORANGE, CA 92665 (714) 974-1920



191


MARIAH AIR PUMP SIZING CHART

960228 CWF6001

MODEL NO.	STAGES	VOLTS	MAX. AMPS	MAX. PSI	MAX. CFM	WATER DEPTH	FLOOR HOLES @ 3/16"	-OR- FLOOR HOLES @ 1/8"	SEAT HOLES @ 1/8"	NO. VENTURI'S
12-1201	1	120	7.2	2.3	153	24"	18	16	35	4-6
12-2401	1	240	3.8	2.3	144	30"	15	13	27	4-6
12-1202	2	120	9.1	4.1	105	24"	30	45	45	6-10
						30"	26	39	40	6-10
12-2402	2	240	4.1	4.1	97	36"	22	33	36	6-10
						48"	19	27	32	6-10
12-1203	3	120	9.8	4.8	90	24"	33	50	50	8-12
						30"	29	43	44	8-12
12-2403	3	240	4.3	4.8	86	36"	25	36	40	8-12
						48"	21	30	35	8-12

- 1) CALCULATIONS ARE FOR A 25' RUN USING 1 1/2" PVC PIPE AND TWO (2) NINETY DEGREE ANGLES. FOR LONGER RUNS, DECREASE QUANTITY BY 10% FOR EACH ADDITIONAL TEN FEET AND 5% FOR EACH ADDITIONAL NINETY DEGREE ANGLE.
- 2) FOR INCREASED ACTION OR IF MORE HOLES THAN LISTED ARE DRILLED, IT MAY BE NECESSARY TO USE TWO AIR PUMPS.
- 3) CALCULATE DEPTH OF WATER TO HIGHEST LEVEL IN SPA.
- 4) IF FEWER HOLES THAN LISTED ARE DRILLED, THE AIR PUMP WILL STILL FUNCTION AS LONG AS A MINIMUM OF 20 3/16" HOLES ARE DRILLED IN THE FLOOR OR SEAT.

MARIAH 120/240 VOLT RESIDENTIAL AIR PUMP FLOW CHART



AIR PUMP USAGE

- 1 H.P. — As an air boost for six (6) jets or for air induction on spas/hot tubs less than 30" deep and 5' x 5' or 25 square feet of surface area.
- 2 H.P. — As an air boost for six (6) to eight (8) jets or for air induction on spas/hot tubs less than 50" deep and 8' x 8' or 70 square feet of surface area.
- 2.5 H.P. — As an air boost for eight (8) to ten (10) jets or for air induction on spas/hot tubs less than 60" deep and 10' x 10' or 100 square feet of surface area.

*NOTE: If the air line consists of more than thirty five (35) lineal feet of pipe, a larger size air pump should be used.

and.
"Ni
has
are
cus
wit
If
the
mu
dea
mo"

An:
Zen
NB.
stop
our
clos
NB.
heir

B
ong
Dist
Big

S

Con
mon.
Prin
A
earn
the
estal
natic
clud
scho
tear
regi
sche
said.
"E
so th
fami
offer
from
dent.
stud
in ter

Officers Recognized

EXHIBIT #7
KTS 3/21/96
960778CWE6001 lice

ed
ony

Potts, ... received the Distinguished Service Medal.

Schoen, 31, was honored for catching a fleeing suspect who allegedly fired a handgun at another officer but failed to hit him.

Officers learned later that the suspect was a parolee who had been involved in a gun battle with Los Angeles County sheriff's deputies in 1990.

Rudisill, 29, and Hunter, 29, were honored for their efforts in breaking up a ring of robbers who stole from pizza delivery people. Posing as pizza deliverymen, the officers were dispatched to a residence in the 200 block of West Valencia Drive, where they were confronted by two men who tried to rob them and fired several gun shots at Rudisill.

The two officers, who were not injured, returned fire. The suspects fled but later were arrested.

Potts, 33, was praised for his efforts, both on and off duty, in presenting training programs for fellow officers and the Special Weapons and Tactics (SWAT) Team.

COUNTYWIDE

Cypress College Cites Couple for Generosity

Business owners Lew and Margaret Webb are Cypress College's Americana Man and Woman of the Year.

The Webbs, who operate eight car dealerships in Orange and Los Angeles counties, were honored by the college for their work in several service organizations and for their financial support of community groups.

Recipients of the Laguna Hills couple's generosity include the American Cancer Society, St. Mary Medical Center Foundation, Casa Youth Shelter and Mission Hills Church.

—BY MIMI KO CHIZ

Northwest

HUNTINGTON BEACH

960728CWE6001

Spa Warnings Reiterated Following Girl's Drowning

The weekend drowning of a 12-year-old girl whose hair got sucked into the vent of a hot tub has prompted renewed warnings about the dangers of spas, especially the older single intake-type built before the enactment of safety codes.

"I've seen several of these [accidents] and every one of them happened in an old-style spa," Donald Boland, a spokesman for the Huntington Beach Fire Department, said Monday of the drowning of [redacted].

"You remember every one of these; it's not like a car accident. These are the things that stick in your mind."

The accident occurred Sunday night at the home of [redacted] on [redacted] where she and her parents were visiting from their home in Houston.

The girl was in the spa alone about 8 p.m., Boland said, when her hair was apparently sucked into an intake valve, and she was pulled underwater.

By the time relatives had cut her hair to free her, the fireman said, she had lost consciousness. She later died at a hospital.

The incident closely resembled another in Villa Park just seven months ago that nearly took the life of the 6-year-old son of former [redacted] player [redacted]. In that case, however, [redacted] was able to save the boy's life by wrenching him free of the drain, which left a 10-inch-diameter bruise on the youngster's back.

The drowning of a 9-year-old boy in 1976 prompted county officials to begin requiring two vents rather than one in all spas built in unincorporated areas.

Designing spas with two vents, said Larry Nees, manager of building inspections for Orange County, significantly decreases the amount of suction in each one.

The county also began requiring that vents be covered and constructed in a manner designed to prevent hair or body parts from being pulled in.

Huntington Beach, where Sunday's drowning occurred, eventually adopted similar standards, said Bill Grove, the city's inspection manager, but not in time to affect construction of the spa in which Sunday's accident occurred.

—DAVID HALDANE

Spa Safety

Here are some precautions to keep in mind if you own a spa:

- Avoid problems with a single drain by installing a second one to disperse suction.
- Install safety dome on flat drains.
- Instruct anyone with long hair not to get it near a drain, and tell anyone who uses your spa not to stick fingers, toes or other body parts into drain.
- Place power switch nearby so it can be reached quickly in case of emergency.
- If your spa is indoors, lock the door to the room or use a cover that locks.
- Closely supervise children, even if they know how to swim.
- If you are concerned about a spa's safety, check with a building inspector.
- For more information, call the Orange County chapter of the National Spa and Pool Institute, (714) 832-1113.

Sources: National Spa and Pool Institute; Children's Hospital of Orange County

Exhibit #8
960228CWE6001
3/19/96

#960228CWE6001

LB 3/21/96

**PRICE
COSTCOSM**

PHOTO CENTER
THE VALUE IN
PHOTOPROCESSING!

- REPRINTS
- ENLARGEMENTS
- JUMBO 4 X 6 PRINTS
- EXTRA PRINTS AT TIME
OF DEVELOPING

Exhibit #8
960228CWE6001
3/19/96




PHOTO #1, BACKYARD SPA-



#2, SPA IN WOODEN DECK. "A" IS FENCE AROUND
EQUIPMENT AREA.

Exhibit #8
960228CWE6001
3/19/96




#3,



#4,

Exhibit #8
960228CWE6001
3/19/96



#7



#8

197

Exhibit #8
960228CWE6001
3/19/96




#9 STEPS LEADING INTO SPA. "C" IS
SECTION HOLE.




#10, SECTION HOLE (WITHOUT COVER) &
LIGHT.

Exhibit #8
960228CWE6001
3/19/96




#11, close-up of light and suction
hole.




#12, close-up of logo on bottom
of STA.

199

Exhibit #8
960228CWE6001
3/19/96



13, WARNING (ACTION) LABEL LOCATED
NEAR TOP STEP.




14, LABEL LOCATED NEAR TOP
STEP.

200

Exhibit #8
960228CWE6001
3/19/96




#17 SECTION COVER, SIDE.



#18, SECTION COVER, BOTTOM.

Exhibit #8
960228CWE6001
3/19/96



#19, EQUIPMENT AREA-





#20

FILTER

202

Exhibit #8
960228CWE6001
3/19/96

21



→ #22 "D" = HEATER, "E" = FILTER PUMP, 203
"F" = PLANTER FERT. INJECT. FILTER

Exhibit #8
960228CWE6001
3/19/96

#23, "G" = BLOWER
"H" = FILTER PUMP
I = FILTER




#24, Jet motor.

Exhibit #8
960228CWE6001
3/19/96




#25, HEATER NAME
PLATE.




#26, HEATER ID PLATE

902

Exhibit #8
960228CWE6001
3/19/96



#15 Suction cover, TOP



#16, Suction cover, TOP.

Feb-27-96 12:40P Product Safety

1 714 588 5934

P.02

Older spa culprit in death of girl, 12

ACCIDENT: The tub apparently lacked safety devices that could have prevented her drowning.

By CAROL MASCOLO
The Orange County Register

HUNTINGTON BEACH —

12, went outside alone to use her grandparents' spa Sunday night and lost her life when her hair was sucked into a drain in the bottom of the tub.

The day after the accident, authorities and spa sellers warned people to destroy or upgrade older spas. A spa should have more than one drain, to diffuse the suction, and each of the drains should be capped with an "anti-vortex" cover to prevent hair and body parts from being trapped.

"It's very, very rare for something like that to happen," said Joe Chandler, owner of Chandler's Pool and Spa Repair in Tustin. "It's just a matter of putting on the right drain cover. Of course, anytime there's a kid in the water, somebody should be supervising."

Firefighters said [redacted] of Houston, Texas, was given permission to use the spa sometime before 8 p.m. Sunday. After about 20 minutes, family members, including the girl's father, noticed that the spa was operating but [redacted] was nowhere to be seen. Her mother was not present.

When they went outside, family members discovered that [redacted] was pinned to the bottom of the spa by her hair. They tried to pull her out but had to cut her hair to free her, police said.

"You can imagine the terror that was going on when the poor child was on the bottom of the (spa) and they couldn't pull her off," said Donald Boland of the Huntington Beach Fire Department. "It must have been a horrible experience for the whole family."

A neighbor who is a nurse said

960228CWE6001

F9626001A

Sect 15

Orange County Register
2/27/96

(2/25/96 SC NTH)

SPA

FROM 1

a policeman tried to resuscitate [redacted]. Paramedics arrived at the grandparents' home on Maui Circle within five minutes. They used cardiopulmonary resuscitation and drug therapy, but were unable to revive the girl. [redacted] was pronounced dead Sunday at Huntington Beach Medical Center.

Huntington Beach and the county have enacted laws that require all new spas to have a minimum of two covered drains. But the laws don't apply to older spas.

"There's no rule that you have to go back and retrofit your older spa," said Chi Tran, manager of the county building-permits division.

Last July, 6-year-old [redacted] was sucked to the bottom of the spa at his Villa Park home and held under three minutes before his father, former Los Angeles Rams player [redacted], pulled him out and resuscitated him. [redacted] said it took him three tries to extricate the boy from the drain.

U. S. CONSUMER PRODUCT SAFETY COMMISSION

AUTHORIZATION FOR RELEASE OF NAME

960 2280 WE 6301

Thank you for assisting us in collecting information on a potential product safety problem. The Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety problems.

We routinely forward this information to manufacturers and private labelers to inform them of the involvement of their product in an accident situation. We also give the information to others requesting information about specific products. Manufacturers need the individual's name so that they can obtain additional information on the product or accident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name. If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

☐

You are hereby authorized to disclose my name and address with the information collected on this case.

☒

My identity is to remain confidential.

[Redacted Signature]

(Signature)

3-21-96

(Date)

208



The American Society Of
Mechanical Engineers

Codes and Standards

212 605-3333
212 605-8750 Fax

345 East 47th Street
New York, NY 10017-2392

COMMITTEE CORRESPONDENCE

February 2, 1996

Judith Hayes (Via Fax)
CPSC Compliance
4330 East West Highway
Bethesda, Md. 20814-4408

*fax 714-228-0465
Kerene Barton's*

Dear Judy,

At the A112.19.7 & 8 working Group meetings in July, 1995 there was discussion of getting input for revising the form used by CPSC for In Depth Investigations, from the Working Group.

The compilation of the responses / suggestions for changes and additions follows below. All of the requests made will yield more meaningful information about incidents involving Suction Covers. Please review the suggestions and let us know what you will incorporate in the IDI Form.

1. Get additional information about the pump.

A. Original or changed?

B. Rating

* Horse Power

* Volts - 220V

* Amps

* Manufacturer and Model Number

C. What type of pump was originally specified by Whirlpool or Spa manufacturer?

* Horse Power

* Volts - ~~220V~~

* Amps

* Manufacturer and Model Number

- unknown if any components changed prior to purchase in 1994. afterwards - no changes by current owners
blower - 120 volts

2. System Information

A. Number of Jets and the name of the Jet Manufacturer.

*7 jets - appears to be adjustable
85" outside
73" inside
36" deep
36" sides
molded seats*

209

* What is the diameter of the interior orifice of the jet.

B. Number of suction fittings and the name of the Manufacturer of the Suction Fitting.

* Are Suction Covers secured properly

* Was Suction Cover Damaged or tampered with prior to accident? — *no signs of tampering.*

* What is Listed Rating of Suction Cover?

** Does it match system flow?

*** Perform in field flow test

* List all markings on Suction Cover / Fitting

* The quantity of holes on the suction cover.

* The diameter of the holes on the suction cover

*Hydro Air
p/n 10-6200
U.S.P.C.
cover 6" in diameter
threaded portion
2 7/8" diam.*

C. Was circulation system installed by manufacturer of bathing vessel or was it installed by an independent jetter.

D. Is the Spa / Whirlpool in question Listed by any Testing Agencies? List all shown on unit.

E. Do any of the components of the system in question appear to have been tampered with? If yes, list component and sign / indication of tampering. *~~no signs of tampering~~*

3. Hair

A. What is length in inches of hair sample in question?

* Free Length

* Length from scalp

B. What is hair type or grade (Color; Thick or Fine, Straight or Curly)

C. What is diameter of single hair strand involved in accident?

D. How much hair was entrapped / entangled (weight in ounces)

E. How was hair worn

* Loose

* Braid


* Pony Tail

* Other (describe)

4. Electric Shock

A. Were there any other electrical devices within reach of the vessel in question?

Sincerely,



David Allen

c: All Members Working Groups A112.19.7 & A112.19.8

Chapman

CPSC 67
AUG-4 P1:31

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

SUMMARY OF FINDINGS:

This limited inspection was performed as a follow-up to an IDI 940627CAA1585 involving where the waist length hair of a 10 year old female became entangled in a bottom drain of a backyard pool/spa as she performed a head stand within the spa. The acrylic spa was manufactured by the subject firm using drains manufactured by Hydro Air Industries Inc., Orange CA.

Inspection disclosed that this firm has been manufacturing spas since 1977, and has been using the Hydro Air drains since 1980. Mr. Ronald K. Norborg, President of the firm stated that prior to this incident, he was not aware of any injuries or deaths attributed to the use of the spas and hot tubs manufactured by this firm. He stated there is no litigation in process.

During the inspection, Mr. Norborg provided instructional information regarding the Model NS-302 Spillway Spa, of the type that was involved in the incident, as well as installation instructions as per provided by Hydro Air Inc. Mr. Norborg also supplied drain assemblies of the Model 10-6200 (bottom drain) and the Model 10-6900 side drain assembly. These assemblies were photographed at the resident office and returned to Mr. Norborg.

Mr. Norborg stated he manufactures approximately 800 Spas and Hot Tubs yearly, his annual volume approximately 1.5 million dollars. He is a wholesaler, selling directly to retailers and installers of spas.

SUMMARY AND TYPE OF BUSINESS:

This firm is a Florida corporation, Mr. Ronald K. Norborg personally holds all of the officer positions in the corporation.

Spas are manufactured pre-plumbed for installation by pool manufacturing companies, when incorporating the spa as an adjunct to the main pool.

The Hot Tubs manufactured here are self contained, pre-plumbed and pre-wired, intended to be portable and plugged directly into the electrical receptacle.

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

I presented my credentials and issued a Notice of Inspection to Mr. K. Norborg, he provided the information for this report and provided the two drains for photographing. As the President of the corporation, Mr. Norborg stated he would be the individual most responsible for the overall operation of this business.

COMPLAINT HISTORY:

I have no previous history on this firm.

PRODUCT GUARANTEES & CERTIFICATION:

Mr. Norborg stated he is a member the National Spa & Pool Institute (NSPI) and as such, follows their recommendation for the design and manufacture of Spas and Hot Tubs. Mr. Norborg's stated that to the best of his knowledge, these spas and hot tubs manufactured here are in compliance with NSPI recommendations.

MANUFACTURING OPERATION:

The spas and hot tubs are manufactured at this location.

PRODUCT LABELLING:

Mr. Norborg supplied promotional literature on the Model SW-304 identified as being manufactured by Spillway Spas, 4300 - D L.B. McLeod Rd., Orlando FL. 32811 Phone number (401) 426-7727. The informational sheet shows that this model is a deep octagon model, 78 inches long by 78 inches wide by 33 inches deep. The water volume is approximately 280 gallons with an overflow design and seats six adults. A copy of the brochure is attached as exhibit #1.

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

In addition Mr. Norborg provided a diagram for the NS-302 showing the spillway, the air channel connection, and the fitting colors as an instructional manual to the spa installers. Please note that on this sheet the side fitting is known as #9, HA slim line side drain. The #12 designation is for a HA 2 inch main drain. This instruction is shown as exhibit 2. Mr. Norborg also provided a copy of the instructional information provided in the Hydro Air 1994 Catalog. The 10-6200 main drain assembly is shown attached as exhibit 3, the 10-6900 slim line suction fitting assembly is shown as exhibit 4. The main drain assembly is designed to be used within the bottom of the pool, while the slim line suction fitting assembly is used in the side of the pool. Please see copies of the actual pool involved in the incident attached to the original indepth investigation. Also obtained were copies of the installation instructions for the 10-6200 main drain. All of this information was obtained from the insert within the valve package. This instruction sheet is attached as exhibit 5.

The instruction sheet for the 10-6900 side drain is attached as exhibit 6.

PRODUCT CODES:

Mr. Norborg stated that all spas and hot tubs are identified with a serial number that is coordinated with the date of manufacturer.

DISTRIBUTION:

Mr. Norborg stated that approximately 80% of the spas and hot tubs manufactured here are distributed within the State of Florida, and an occasional 10% going outside of Florida. He has one Manufacture Representative to promote the sales of these spas and hot tubs. He stated that other than the descriptive literature such as provided during the inspection, he does no other promotions or advertising.

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

SAMPLES COLLECTED:

No samples were collected, however Mr. Norborg provided both drains for photographing. Both drains were photographed at the Resident Office and returned to Mr. Norborg.

STANDARDS:

I am not aware of any mandatory CPSC Standards, however an NSPI has recommendations for the design and manufacture of spas and hot tubs.

DISCUSSION WITH MANAGEMENT:

I discussed with Mr. Norborg, that the purpose of the inspection was a follow-up to the incident involving a 10 year old female whose hair became entrapped in the bottom drain of a spa manufactured by his firm and installed as part of a pool/spa complex by an outside, independent pool manufacturer. Mr. Norborg was aware of the incident, and stated he had spoken directly with the installer. They both came to the conclusion that the spa was not at fault, but was misused by the 10 year old female who performed a hand stand directly over the bottom drain, thus allowing her waist length hair to become entangled in the bottom suction drain. Both of the installer, and the spa manufacture feel that the design of the spa is safe when used as intended, for sit down relaxation. Mr. Norborg was aware that Hydro Air, the manufacture of the bottom drain had also been informed of the incident by the pool installer.

I had a question on the installation of the #10-6900 Slim Line suction fitting assembly that was installed in the side of the pool area. I noted that the instruction sheet, exhibit 2, shows that this assembly is adding water to the pool, however the installer stated that this side assembly was actually a second drain, the first drain being the main bottom drain.

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

Mr. Norborg stated the spa is designed to have only the one, main bottom drain and is intended to be installed as such. However, Mr. Norborg stated that due to the design of the spa, and the various fittings, it would be possible to make the side fitting either an inlet or outlet depending on the plumbing, and the number of pumps involved. In the aforementioned installation, there was a separate 1 1/2 horsepower pump serving the spa, with a separate 1 horsepower pump serving the main drain. I informed Mr. Norborg that the spa owner stated that the side fitting pumping water into the spa, while the installer stated the side fitting was actually taking water out of the spa.

Mr. Norborg telephoned the installer during the inspection, and asked him if the side fitting was an input or output fixture. The installer stated, that to the best of his knowledge, the side fixture was a second drain, in addition to the main drain. The installer had told me previously that they prefer to plumb the spas so that there are two suction drains. During the telephone conversation, it became clear that the installer was not sure whether the side drain was an inlet or outlet. Please note, that the spa owner stated the side fixture was adding water to the spa, the installer stated the side fixture was removing water from the spa, and the spa manufacturer stated that the side fitting was designed to add water to the pool.

The pool installer stated he will personally visit the homeowner and determine if the side fixture is adding or subtracting water from the spa and so inform me. This information, when provided will be supplemented to this report.

Baker Manufacturing Corp.
4300 - D L.B. McLeod Rd.
Orlando, FL. 32811
94027CAA1585-J
7/6/94 EJM

EXHIBITS:

The following exhibits are attached to this report:

1. Informational material on the Spillway Spa Model # SW-302. Note the photograph in the lower right hand corner of the brochure is very similar to the set-up at the accident site.
2. Instructional material covering the MS-302-Fitting Color showing the various inlets and outlets involved in the installation of this spa.
3. Photostat of the Hydro Air 1994 Catalog depicting the Model 10-6200 Main Drain assembly used in the bottom of the Spa.
4. Photostat from the 1994 Hydro Air Catalog depicting the Model 10-6900 Slim Line Suction Fitting assembly. This assembly was installed on the side of the pool and there is some discussion as to whether this was a power or suction fitting.
5. Package insert with the #10-6200 Main Drain Package
6. Package insert for the #10-6900 Suction Fitting Installation instructions.
7. Photographs of the above mentioned two fittings.

Also attached to this report is a copy of the Notice of Inspection.


Edward J. Morganto,
Resident Investigator
ORL/ Res. Off.

EJM/ph

Model SW-302

Sit back, relax and enjoy the luxuriously designed continuous seating offered in this SPILLWAY spa. Thanks to its spaciousness, this spa allows you to share refreshing moments and conversation with as many as five adults. The smooth circular design offers you and your guests equally comfortable seating arrangements including glove soft pillow headrests. A spa where every position provides the perfect combination of natural relaxation and comfort.

78" L x 78" W x 33" Deep Octagon
Water Volume Approximately 280 Gallons
Overflow Design
Velvet 2" Air (Channel) Jet System
Seats 6 Adults
Bi-Level Continuous Sofa Contours
2 Recessed Pillows
Slip Resistant Steps & Bottom




Right hand models shown here
Left hand models available




Model SW-304

The simplicity and elegance of this SPILLWAY spa add to the spectacular feeling that comes naturally from using it. Able to accommodate up to eight adults, this spacious spa is often the "people's choice" as an entertainment center. Unique dual seating enhances your pleasure by providing smooth sofa contours on one side, relaxing lounge contours on the other. Glove soft pillows provide a comfortable headrest. You'll create a whole new lifestyle — a naturally healthy style — in this SPILLWAY spa.

90" L x 90" W x 34" Deep Octagon
Water Volume Approximately 400 Gallons
Overflow Design
Velvet 2" Air (Channel) Jet System
Seats 8 Adults
Continuous Sofa Contour
Continuous Lounge Contour
2 Recessed Pillows
Slip Resistant Steps & Bottom




DAVE L. MANUFACTURING CORP
CALABASO, FL 33909
940627CAA1585 J



4300-D L.B. McLeod Road • Orlando, Florida 32811
Spas (407) 426-7727 • Fax (407) 246-0471 • (800) 881-2284

EXHIBIT 2



NS-302

FITTING COLOR:

MFG. KEY

- *1 THRU 8 - HY PRO JETS
- *9 - HA SLIM LINE SIDE DRAIN
- *10 - HA 1" AIR CONTROL
(FOR JETS *1 THRU 4)
- *11 - HA 1" AIR CONTROL
(FOR JETS *5 THRU 8)
- *12 - HA 2" MAIN DRAIN

- $1\frac{1}{2}$ " ϕ PIPE FOR JETS - WATER
(STUB W/2 ϕ)
- 1" ϕ PIPE FOR JETS - AIR
- $1\frac{1}{2}$ " ϕ PIPE STUB FOR *9
- 2" ϕ PIPE STUB FOR *12
- 2" ϕ PIPE STUB FOR AIR CHAN.

HYDRO AIR INDUSTRIES, INC.
ORLANDO, FL 7/6/94 EJM
940627CAA1361

Includes mounting hardware.
5 per bag, 1 lb. 2 oz.

10-6002

Thru-Floor Fitting only

1-1/4" thread length.
10 per bag, 2 lbs. 4 oz.

10-6302

Extended Main Drain
Fitting only

2-1/4" thread length.
5 per bag, 1 lb. 13 oz.

10-6003

Gasket for Main Drain

Also fits swim jet & adjustable
skimmer. 1 oz. ea.

10-6004


1-1/2" x 2" Slip Tee Main Drain
Nut Fitting

12 oz. ea.

10-6010

Main Drain Fitting Nut


Fits #6302 & 6002.
1 oz. ea.



With nut, includes all
mounting hardware.

10-6204

Extended Main Drain
with Lock Nut



10-6209

(4) Main Drain
Screws

10-1060

TEST PLUG for Main Drain

See page 29.

W/mounting hardware, 1-1/2"
& 2" plugs. 20/case, 31 lbs.

Not pictured:

10-6203

Extended Main Drain
Assembly


Includes all mounting hardware,
1-1/2" & 2" plugs. 20/case, 32 lbs.

10-6104
Straight Nut PVC

For suction or inlet. 1-1/2"
socket X 2" spigot. 4 oz. ea.

10-6103 90° Nut

10-6500 Skimmer



10-1038
Test Plug
See page 29.

Incl. 10-6521, 6520, 3801, 3804, 6104 & screws.
30/case, 25 lbs.

10-6530 Extended Skimmer w/Straight Nut w/Screws

10-6600
Adjustable Skimmer w/Straight Nut

10-6609
Adjustable Skimmer w/90° Nut

10-6520

Skimmer Face Plate only

5 oz. ea.

10-6521

Gate for Skimmer

Fits #6520,
1 oz. ea.

10-6503

Skimmer Mounting Screw

#8 x 1-3/4" Phillips flat S/S.

10-6111SS

Skimmer Gate Screw


#4 x 3/4" Phillips flat S/St.

Skimmer Metal
Escalation



10-6520MF
Fits #6500, 6509, 6530 &
6539. 10 oz. ea.

10-6539 Skimmer



Incl. 90° nut, screws. 1-1/2" socket
X 2" spigot. 30 per case, 29 lbs.


10-6539

Extended 90° Skimmer w/screws

CHART 1

*was used as
a return
not suction*

10-6900 Slimline Suction Fitting Assembly



Includes thru-wall fitting, cover & straight fitting nut. 1-1/2" socket X 2" spigot. 100/case, 42 lbs.

Not pictured: 10-6909 90° Slimline Suction Fitting. Same as 6900, w/ 90° nut; 60/case, 36 lbs.

10-6104 Straight Nut PVC

For suction or inlet. 1-1/2" socket X 2" spigot. 4 oz. ea.

Not pictured:

10-6103 90° Nut PVC

10-3804

Wall Fitting Gasket

Fits Suction Fitting, Standard Fitting & Skimmer. 1 oz. ea.

10-6908 Slimline Suction Fitting only

10-6903
Slimline Suction Fitting,
Extended, w/2-1/4" Threads

10-6906 Slimline Suction Cover

10/bag, 240/case.

10-6930

Extended Slimline Suction Assembly

Includes extended fitting, cover & straight nut. 1-1/2" socket X 2" spigot. 70/case, 36 lbs.

10-6939

Extended Slimline Suction Assembly w/90° Nut


Includes extended fitting, cover & 90° nut. 1-1/2" socket X 2" spigot. 50/case, 34 lbs.

10-6930LK

Extended Slimline Suction Fitting Assembly w/Lock Nut


10-6900M Metal Slimline Suction Fitting Assembly

Includes metal cover, fitting, straight nut & gasket. 1-1/2" socket X 2" spigot.



100/case, 48 lbs.

10-6919 Slimline Suction Fitting Assembly w/Offset Nut



Includes cover, fitting, 10° offset straight nut & gasket. 70/case, 37 lbs.

10-7301SS

Stainless Steel Slimline Suction Screw

10-6909M

90° Metal Slimline Suction Fitting Assembly
60/case.

10-6930M

Extended Metal Slimline Suction Fitting Assembly
70/case.

10-6939M

Extended 90° Metal Slimline Suction Fitting Assembly
50/case.

10-6906M

Metal Slimline Suction Cover



Incl. 3-1/2" dia. anti-vortex metal cover (3/8" h) & adaptor. 200/case.

10-6920

Test Plug for Slimline Suction

See Page 29.

12

HYDRO AIR INDUSTRIES INC.



OK 5
-BAKER MANUFACTURING CORP
ORLANDO, FL 7/6/94 EJM
940627CAA1585 J

10-6200 Hair Dredge
Package Insert.

SUCTION FITTING INSTALLATION INSTRUCTIONS

INSTALLATION:


- 1.) Making sure the surface is flat for best possible seal, drill a hole to suit the wall fitting being installed.

RECOMMENDED HOLE SAW SIZES ARE:

#10-6106 & 10-6106M	STANDARD SUCTION	2 9/16"
#10-6906 & 10-6906M	SLIMLINE SUCTION	2 9/16"
#10-6806 & 10-6806M	HI VOLUME SUCTION	2 9/16"
#10-6001	MAIN DRAIN	3"

NOTE: SEE REVERSE SIDE FOR PROPER SUCTION FITTING ASSEMBLIES.

- 2.) The gasket, when used, should be placed on the outside surface of the spa/tub. On a radius, the gasket should be placed on the inside of spa/tub to obtain the best seal. Make sure the sealing surface is smooth to provide for a good seal.
- 3.) Before inserting the wall fitting through the hole, apply silicone to the threads. This will help seal the wall fitting and the nut.
- 4.) Using a wrench, hand tighten the wall fitting into the nut. It is not necessary to overtighten as the gasket and silicone will create a good seal.
- 5.) Screw the suction cover with threaded adapter into wall fitting until adapter bottoms out. On the Slimline model, #10-6906 & 10-6906M, the cover will lock automatically when fully tightened. All other models require the locking screw to be placed through the face of the cover in the provided hole, and tightened until the cover is secure.
- 6.) To remove the cover, on Slimline models, lift the latch at the side of the cover while rotating counter clockwise. Other models require the removal of the locking screw and then rotating the cover counter clockwise.



NOTE: To reduce the risk of drowning from hair and body entrapment, install a suction fitting(s) with a marked flow rate in gallons per minute that equals or exceeds the flow rate of your system


NOTICE TO BATHER

- 1.) Keep hair and clothing a minimum of twelve inches away from the suction fitting at all times. Persons with long hair should either secure hair to a minimum length or wear a bathing cap.
- 2.) Children should NEVER use or be left unattended at any time in a swimming pool, spa, hot tub, whirlpool or jetted bathtub.


AS WITH ANY BODY OF WATER, A BATHER SHOULD NEVER USE IT ALONE OR WITHOUT SUPERVISION.

SUCTION FITTING MODEL NUMBERS 10-6806 AND 10-6806M SHALL CONSIST OF ONE COMPONENT FROM EACH GROUP.


NUTS




10-6104 STRAIGHT NUT



10-3807 LOCK NUT




10-6103 90° NUT




10-6105 10° OFFSET NUT

WALL FITTINGS




10-3801 STANDARD WALL FITTING




10-3803 EXTENDED STANDARD FITTING

SUCTION COVERS



30-6806 HI VOLUME SUCTION COVER




30-6806M HI VOLUME METAL SUCTION COVER


*Replaced
6106 in
CA 92-86 cu*

SUCTION FITTING MODEL NUMBERS 10-6106 AND 10-6106 M SHALL CONSIST OF ONE COMPONENT FROM EACH GROUP:


NUTS




10-6104 STRAIGHT NUT



10-3807 LOCK NUT




10-6103 90° NUT




10-6105 10° OFFSET NUT

WALL FITTINGS



10-3801 STANDARD WALL FITTING




10-3803 EXTENDED STANDARD FITTING

SUCTION COVERS



30-6106 STANDARD SUCTION COVER




30-6106 M STANDARD METAL SUCTION COVER


*case
CA 92 0056
near drawings
shipped back
in 4/92*

SUCTION FITTING MODEL NUMBERS 10-6906 AND 10-6906M SHALL CONSIST OF ONE COMPONENT FROM EACH GROUP:


NUTS




10-6104 STRAIGHT NUT



10-6105 10° OFFSET NUT




10-6103 90° NUT




10-3807 LOCK NUT

WALL FITTINGS




10-6908 SLIMLINE SUCTION WALL FITTING




10-6903 EXTENDED SLIMLINE

SUCTION COVERS



30-6906 M SLIMLINE METAL SUCTION COVER



30-6906 SLIMLINE SUCTION

*no staff
instruct.
to det*

EXHIBIT 4
-BAKER MANUFACTURING CORP
ORLANDO, FL 7/6/94 EIM
940627CAA1585 J

10-6700
PACIFIC POWER
SIDE FITTING



SUCTION FITTING INSTALLATION INSTRUCTIONS

INSTALLATION:

- 1.) Making sure the surface is flat for best possible seal, drill a hole to suit the wall fitting being installed.


RECOMMENDED HOLE SAW SIZES ARE:

#10-6106 & 10-6106M	STANDARD SUCTION	2 9/16"
#10-6906 & 10-6906M	SLIMLINE SUCTION	2 9/16"
#10-6406 & 10-6406M	HI FLOW SUCTION	3"
#10-6001	MAIN DRAIN	3"

- 2.) The gasket, when used, should be placed on the outside surface of the spa/tub. On a radius, the gasket should be placed on the inside of spa/tub to obtain the best seal. Make sure the sealing surface is smooth to provide for a good seal.
- 3.) Before inserting the wall fitting through the hole, apply silicone to the threads. This will help seal the wall fitting and the nut.
- 4.) Using a wrench, hand tighten the wall fitting into the nut. It is not necessary to over tighten as the gasket and silicone will create a good seal.

(See reverse side)

- 5.) Screw the suction cover with threaded adapter into wall fitting until adapter bottoms out. On the Slimline model, #10-6906 & 10-6906M, the cover will lock automatically when fully tightened. All other models require the locking screw to be placed through the face of the cover in the provided hole, and tightened until the cover is secure.
- 6.) To remove the cover, on Slimline models, lift the latch at the side of the cover while rotating counter clockwise. Other models require the removal of the locking screw and then rotating the cover counter clockwise.



NOTE: To reduce the risk of drowning from hair and body entrapment, install a suction fitting(s) with a marked flow rate in gallons per minute that equals or exceeds the flow rate of your system.

NOTICE TO BATHER

- 1.) Keep hair and clothing a minimum of twelve inches away from the suction fitting at all times. Persons with long hair should either secure hair to a minimum length or wear a bathing cap.
- 2.) Children should NEVER use or be left unattended at any time in a swimming pool, spa, hot tub, whirlpool or jetted bathtub.

AS WITH ANY BODY OF WATER, A BATHER SHOULD NEVER USE IT ALONE OR WITHOUT SUPERVISION.

-BAKER MANUFACTURING CORP
ORLANDO, FL 7/6/94 EJM
940627CAA1585 J





PHOTO 1 MAIN(BOTTOM) DRAIN IN THE SPA. WHEN VIEWING THESE PHOTOS, PLEASE REFER TO THE ATTACHED INFORMATION SHEET FOR "10-6200 Main Drain Assembly". Drain shown here is assembled position. Note either end of the Tee connection can be blocked depending on the intended use.

PHOTO 2 AS ABOVE



DAVEY MANUFACTURING CORP
DAVEY, FL 7/6/94 EJM
940627CAA1585 J

57




PHOTO 2 DOMED COVER. 6 INCHES IN DIAMETER

PHOTO 4 AS ABOVE

